



Report No.	:	UKC0000001E Re - Inspection
Client Name	:	UK1st Choice
Order / P.O / P.I No.	:	N/A
Product Description	:	Furniture
Product Item / Part No.	:	9310,9605,9308,9655,9628,9365,9509,9513
Product Quantity	:	720Unit
Supplier Name	:	Bazhou Hetai Furniture CO.,LTD
Inspection Date	:	2015-08-21
Inspection Location	:	Bazhou City , Hebei Province , China

WORKMANSHIP INSPECTION PLAN AND DEFECTS QTY

Inspection Standar	d: A	NSI/ASQC Z 1.4-2003	AQ	L S	tandard	Allow Defects QTY	Actual Defects QTY
Sampling Plan	:	Single Normal	Critical	:	0	0	0
Inspection Level	:	GII	Major	:	2.5	5	8
Total Sample Size	4	80	Minor	:	4.0	7	3

INSPECTION DETAILS RESULT

1)	QUANTITY		Conform
2)	WORKMANSHIP		Not Conform, Refer to AQL 3 4/5
3)	ARTWORKS	:	Conform
4)	PACKAGING	:	Not Conform, Refer to Special Attentions:3
5)	SHPPING MARK	:	Conform
6)	TESTING / DATA MEASUREMENT	:	Not Conform, Refer to Special Attentions:1&2

INSPECTION OVERALL CONCLUSION : ACCEPTED PENDING FAILED X

	SPECIAL ATTENTION
1	The factory does not accept drop test
2.	Moisture content test was a failed Refer Pic.A-D
3	Model 9509 PI description is coffee table , shipping mark is TV stand but actual is dining table Refer Pic.E-F
4	Model 9513 legs there are have wooden scar is more than AQL Pic.G-J
5	Surface have Chinese fittings bag Pic.I-M
6	

Name(s) of Inspec	ctor(s)		Name of Reviewer		
2015-08-21	Andy Xu	Andy	2015-08-24	Chuck Shi	Chuck shi
Date	Name	Signature	Date	Name	Signature

The inspection report reflects our findings at the time and place of inspection. This report does not relieve the seller/manufacturer of their contractual liabilities or prejudice from the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter.

HONOR INSPECTION
INTERNATIONAL LTD. NINGBO
REPRESENTATIVE OFFICE.

Rm.604,10th,Building,RongAnHeYuan No.306,SongJiangDong-Road,YinZhou Distric,NingBo City,China.

Tel: +86-574-88197698 Fax: +86-574-88197638-8

Email: report@honorinspection.com Web: www.honorinspection.com Report Version:20150606

Page 1 of 71





Special Attention Refer Photos



Pic.A Moisture content test was a failed



Pic.B Moisture content test was a failed



Pic.C Moisture content test was a failed



Pic.D Moisture content test was a failed



Pic.E Model 9509 PI description is coffee table , shipping mark is TV stand but actual is dining table



Pic.F Model 9509 PI description is coffee table, shipping mark is TV stand but actual is dining table







Pic.G Model 9513 legs there are have wooden scar is more than AQL



Pic.H Model 9513 legs there are have wooden scar is more than AQL



Pic.I Model 9513 legs there are have wooden scar is more than AQL



Pic.J Model 9513 legs there are have wooden scar is more than AQL



Pic.I Surface have Chinese fittings bag



Pic.M Surface have Chinese fittings bag





RANDOM SAMPLING PLAN FOR EACH ITEM

1) Result:	QUANTITY Conform						
No.	Item / Part No.	Order Quantity	Packed Quantity	Not packed Quantity	Not finished Quantity	Samp Packed Quantity	ling Size Not packed QTY
1	9310	100	100	0	0	10	0
2	9605	150	150	0	0	12	0
3	9308	50	50	0	0	5	0
4	9655	50	50	0	0	5	0
5	9628	50	50	0	0	5	0
6	9365	50	50	0	0	5	0
7	9509	50	50	0	0	5	0
8	9513	220	220	0	0	33	0
	Total	720	720	0	0	80	0
	Total			0 ere found out of s	_	80	

2) WORKMANSHIP Result: Not Conform, Fafer to AQL \$ 45 Defects Description Critical Major Minor Item No.: 9605 Defects QTTV Hole is not clean (Pls. see Pic.1) 1 2 1 1 2 1 1 2 1 1 2 1 1 2 1 1 2 1 1 2 1 2 1 2 1 2 2 2 2 2 <th cols<="" th=""><th>The inspection details were round as follows:</th><th></th><th></th><th></th></th>	<th>The inspection details were round as follows:</th> <th></th> <th></th> <th></th>	The inspection details were round as follows:			
Defects Description Critical Major Minor Item No.: 9605 Defects QTY Hole is not clean (Pls. see Pic.1) 1 1 Leg is not smooth (Pls. see Pic.2) 3 0 1 Surface is scratched (Pls. see Pic.3) 0 1 2 Item No.: 9655 Defects QTY 0 1 0 On the surface of the wear (Pls. see Pic.4) 0 1 0 1 0 Item No.: 9513 Defects QTY legs there are have wooden scar (Pls. see Pic.5-11) 0 6 0 Surface is dent 0 0 1 1 0 1 Total Defects Found: 0 8 3	2) WORKMANSHIP				
Item No.: 9605 Defects QTY Hole is not clean (Pls. see Pic.1) 1 0 1 Leg is not smooth (Pls. see Pic.2) 0 1 0 1 Surface is scratched (Pls. see Pic.3) 0 1 2 Item No.: 9655 Defects QTY 0 1 0 On the surface of the wear (Pls. see Pic.4) 0 1 0 1 0 Item No.: 9513 Defects QTY 1 0 6 0 Surface is dent 0 6 0 0 1 1 Individual Total Found: 0 6 1	Result: Not Conform, Fefer to AQL 8.4.5				
Hole is not clean (Pls. see Pic.1) Leg is not smooth (Pls. see Pic.2) Surface is scratched (Pls. see Pic.3) Individual Total Found: On the surface of the wear (Pls. see Pic.4) Individual Total Found: Individual Total Found: On the surface of the wear (Pls. see Pic.4) Individual Total Found: On the surface of the wear (Pls. see Pic.5-11) Individual Total Found: On the surface of the wear (Pls. see Pic.5-11) Individual Total Found: On the surface of the wear (Pls. see Pic.5-11) Individual Total Found: On the surface of the wear (Pls. see Pic.5-11) Individual Total Found: On the surface of the wear (Pls. see Pic.5-11) Individual Total Found: On the surface of the wear (Pls. see Pic.5-11) Individual Total Found: On the surface of the wear (Pls. see Pic.5-11) Individual Total Found: On the surface of the wear (Pls. see Pic.5-11) Individual Total Found: On the surface of the wear (Pls. see Pic.5-11) Individual Total Found: On the surface of the wear (Pls. see Pic.5-11) Individual Total Found: On the surface of the wear (Pls. see Pic.5-11) Individual Total Found: On the surface of the wear (Pls. see Pic.5-11) Individual Total Found: On the surface of the wear (Pls. see Pic.5-11) Individual Total Found: On the surface of the wear (Pls. see Pic.5-11)	Defects Description	Critical	Major	Minor	
Leg is not smooth (Pls. see Pic.2) 1 Surface is scratched (Pls. see Pic.3) 0 Individual Total Found: 0 1 On the surface of the wear (Pls. see Pic.4) 0 1 0 Item No.: 9513 Defects QTY legs there are have wooden scar (Pls. see Pic.5-11) 0 6 0 Surface is dent 0 0 1 Individual Total Found: 0 6 1	Item No.: 9605	De	ects QT	Υ	
Surface is scratched (Pls. see Pic.3) Individual Total Found: 0 1 2 Item No.: 9655 Defects QTY On the surface of the wear (Pls. see Pic.4) 0 1 0 Item No.: 9513 Defects QTY legs there are have wooden scar (Pls. see Pic.5-11) 0 6 0 Surface is dent 0 0 1 Individual Total Found: 0 6 1 Total Defects Found: 0 8 3	Hole is not clean (Pls. see Pic.1)	0	0	1	
Item No.: 9655 Defects QTY On the surface of the wear (Pls. see Pic.4) 0 1 0 Item No.: 9513 Defects QTY legs there are have wooden scar (Pls. see Pic.5-11) 0 6 0 Surface is dent 0 0 1 Individual Total Found: 0 6 1 Total Defects Found: 0 8 3	Leg is not smooth (Pls. see Pic.2)	50	2	1	
Item No.: 9655 Defects QTY On the surface of the wear (Pls. see Pic.4) 0 1 0 Item No.: 9513 Defects QTY legs there are have wooden scar (Pls. see Pic.5-11) 0 6 0 Surface is dent 0 0 1 Individual Total Found: 0 6 1 Total Defects Found: 0 8 3	Surface is scratched (Pls. see Pic.3)	0	V	0	
Item No.: 9513 Defects QTY legs there are have wooden scar (Pls. see Pic.5-11) 0 0 0 0 0 0 0 0 0 1 0 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 0 1 0 0 0 0 0 1 0	Individual Total Found:	0	1	2	
Item No.: 9513 Defects QTY legs there are have wooden scar (Pls. see Pic.5-11) 0 6 0 Surface is dent 0 0 1 Individual Total Found: 0 6 1 Total Defects Found: 0 8 3	Item No.: 9655	De	fects QT	Υ	
Item No.: 9513 Defects QTY legs there are have wooden scar (Pls. see Pic.5-11) 0 6 0 Surface is dent 0 0 1 Individual Total Found: 0 6 1 Total Defects Found: 0 8 3	On the surface of the wear (Pls. see Pic.4)	0	1	0	
legs there are have wooden scar (Pls. see Pic.5-11) Surface is dent Individual Total Found: Total Defects Found: 0 6 0 0 1 1	Individual Total Found:	0	1	0	
Surface is dent Individual Total Found: Total Defects Found: 0 0 1 1 1 0 8 3	Item No.: 9513	De	efects QT	Υ	
Individual Total Found: 0 6 1 Total Defects Found: 0 8 3	legs there are have wooden scar (Pls. see Pic.5-11)	0	6	0	
Total Defects Found: 0 8 3	Surface is dent	0	0	1	
	Individual Total Found:	0	6	1	
	Total Defeate Found	0.	0	2	
AQL Standard Allowed: 5 7	77111 271331 27131				
	AQL Standard Allowed:	0	5	7	





Appearance Defects Refer Photos





Pic.1 Hole is not clean

Pic.2 Leg is not smooth





Pic.3 On the surface of the wear

Pic.4 Surface scratched





Pic.5 Surface is dent

Pic.6 Screw installation is not smooth







Pic.7 Legs there are have wooden scar



Pic.8 Legs there are have wooden scar



Pic.9 Legs there are have wooden scar



Pic.10 Legs there are have wooden scar



Pic.11 Legs there are have wooden scar



Pic.12 Surface is dent





3)	ARTWORKS	
Result:	Conform	
	Markings/ logos/ labels on the gift box	Conform
	Markings/ logos/ labels on the product	Conform
	Color of product	Conform
	Instruction Manual	Conform
	Barcode/ QR code	Conform

Barcode Readabili	ty Check			(80	Sar	nples)	N/A	
Item No	Specification	Actual	Item	No			Speci	ficat	ion	Actual
No have barcode										
	Data Re	ed color marked was/v	vere f	ounc	out of	specif	ication			

4)	PACKAGING			
Result:	Not Conform, Re	fer to Special Attentions:3		
Item No		Accessories	Unit Packing	Unit per Carton
	9310	5 layer carton	1/2	2
	9605	5 layer carton	1/1	1
	9308	5 layer carton	1/1	1
	9655	5 layer carton	1/1	1
	9628	5 layer carton	1/1	1
	9365	5 layer carton	1/1	1
	9509	5 layer carton		1
	9513	5 layer carton	2/1	2
		Data Red color marked was/were	found out of specification.	

rton (L×W×H cm)		(8	(8 Samples) Conform				
Specification	Actual	Item No	Specification	Actual			
N/A	127X47X17	9628	N/A	121.5X59X8			
N/A	128X66X11	9365	N/A	98.5X99.5X9.5			
N/A	168X47X13 164.5X52X10	9509	N/A	90X91X12			
N/A	56X56X14	9513	N/A	80X69X16			
	Specification N/A N/A N/A	Specification Actual N/A 127X47X17 N/A 128X66X11 N/A 168X47X13 164.5X52X10	Specification Actual Item No N/A 127X47X17 9628 N/A 128X66X11 9365 N/A 168X47X13 9509 N/A 56X56X14 9509	Specification Actual Item No Specification N/A 127X47X17 9628 N/A N/A 128X66X11 9365 N/A N/A 168X47X13 9509 N/A N/A 56X56X14 N/A N/A			

Weight of carton	(Kgs)	(8	(8 Samples) Conform				
Item No	Specification	Actual	Item No	Specification	Actual		
9310	N/A	30.7	9628	N/A	10.3		
9605	N/A	29.8	9365	N/A	13.75		
9308	N/A	55.45	9509	N/A	18.25		
9655	N/A	11.35	9513	N/A	11.35		





5)	SHIPPING MARK						
Result:	Conform						
	Main marking	Side marking					
100							
A	breo						
0	1: :- F:						
5	candinavian Furniture						
3333							
S	KU:TV Stand SC9308						

6)	TESTING / DATA MEASUREMENT				
Result	Not Conform,				
	Install the test	(8	Samples)	Conform
	level of the test	(8	Samples)	Conform
	Size test	(10	Samples)	Conform
	moisture content test 8%-12%	1	10	Samples)	Not Conform
	Loading test	1	10	Samples	Conform
	Product inside check	(10	Samples)	Conform
	Drop test on outer carton (H=XX cm)	(0	Carton	Not Conform





PRODUCT REFER PHOTOS





Factory view




Finished product



Inspector in factory









Carton length













Carton inner view
















Shipping mark

Carton inner view



5 layer carton



Carton inner view



Carton inner view




Carton inner view









assembly





































Thickness is 18mm



moisture content test



Product NW





Loading test

Nil

Nil

9310















Carton GW





Carton GW is 30.7kgs

Carton inner view





Carton inner view

Carton inner view



























Assembly&hardware

Is assembling







Product view





Is assembling

Is assembling







Product view

Product view





















moisture content test



moisture content test





Product NW is26.75kgs



Loading test









Loading test

Loading test







Carton view

Shipping mark






Carton length

Carton length is 99cm







Carton GW is 13.75kgs

Carton inner view

























Product NW

Product NW is 10.95kgs



Nil

Loading test





Carton view



Shipping mark























Hardware & assembly

assembly



Sah

Is assembling

Product view







Product view













Thickness is 18cm



moisture content test



moisture content test



Product NW



Product NW is 15.35kgs



Loading test

9513








Carton length

Carton length is 80cm










REPORTE

TEM NO. SET NO.





)







Carton inner view

Carton inner view





Carton inner view

assemb





Assembly&hardware

Is assembling




























Product NW

PRODUCT NW is 4.75kgs

Nil



Loading test



9605



Carton view

Abreo
Scandinavian Furniture
SKU:TV Stand SC9605

Shipping mark















Product GW is 29.8kgs

Carton inner view







Carton inner view

Carton inne view







Carton inner view

































Humidity test

Product NW



Product NW is 27.1kgs



Loading tes



Carton view



Carton view
















Product GW is10.3kgs






Carton inner view

Carton inner view





Carton inner view

Assembly













7 8 9 501 2 3 4 5

Product width

Product width is 50cm





Product height

Product height is 40cm



Thickness of table top is 18.43mm



Humidity test









Humidity test

Product NW



Product NW is 8.35kgs



Thickness of table top is 18.5mm



Loading test

Nil


Nil

9655



















Carton height is 14cm

Product GW







Product GW is 11.35kgs

Carton inner view






Carton inner view

Carton inner view










Carton inner view





Carton inner view

Carton inner view





Assembly

Leg view


























Diameter of table is 30cm



Product height



Product height is 56cm



Thickness of table top is 18,47 mm



Humidity test



Humidity test









Product NW

Product NW is 9.65kgs



Loading test




Nil












moisture content test

KT-50

moisture content test







moisture content test



moisture content test



moisture content test







Loading test

Loading test







-This is end of Report-